

July 08, 2013

Stuart Wood Ventures Ltd.  
9103 - 109 Avenue  
Fort St. John, B.C.  
V1J 7A8

---

**Certificate of Conformance**

<b>Rig No.:</b>	N/A
<b>Equipment:</b>	Casing Elevator - 150 Ton
<b>Model:</b>	9 5/8" SLX-150 Side Door
<b>Customer P.O.:</b>	N/A
<b>Serial No.:</b>	20621
<b>Inspection Report No.:</b>	H-N/A
<b>Alco Sales/Engineering No.:</b>	34969-1-E
<b>APEGGA Permit to Practice No.:</b>	P10702
<b>Alco Shop Work Order # :</b>	N/A

---

This document specifies that all parts and/or assemblies for the equipment referenced above are sold under the manufacturer's warranty.

The above referenced items are to be used according to the manufacturer's directions and ratings. Alco assumes no responsibility for defective parts or assemblies or any costs associated with their repair due to normal use or misuse.

A CAODC Recommended Practice Level IV inspection is typically required after: 500 operating days.

Manufacture's documentation indicate a load test to 1.5 times this component's rating has been done.

