From:

Blackwell, Tim W.

Sent:

Wednesday, October 12, 2016 4:20 PM

To:

Lee, Donald H.

Cc:

Martin, Gregory R.; Reaves, Stacy G.

Subject:

RE: Units 1226 and 21615

Don,

Greg and I walked in the back to take a look at the damage to the trailer and also the unit that was towing the trailer, can you get some photos of the wiring harness that is shredded and also damage to the rear bumper of the unit towing the trailer before it leaves the shop. Did the trailer make contact with the passenger side rear bumper? What caused the trailer to become disconnected from the ball? Was there a pin in the latch to prevent the trailer from becoming disconnected? These are questions that the insurance company are asking.

Thanks, Tim

From: Lee, Donald H.

Sent: Wednesday, October 12, 2016 3:41 PM

To: Blackwell, Tim W.

**Cc:** Martin, Gregory R.; Reaves, Stacy G. **Subject:** RE: Units 1226 and 21615

Thanks I'll meet with you tomorrow to review the incident.

#### Donald H. Lee

Fleet Manager County of Hanover General Services Department, Fleet Division W: (804) 365-6505 / C: (804) 339-5629 11375 Lakeridge Pkwy. Ashland, VA 23005

Hanover: People, Tradition and Spirit

Hanover County VA

From: Blackwell, Tim W.

**Sent:** Wednesday, October 12, 2016 3:30 PM **To:** Lee, Donald H. < <a href="mailto:dhlee@hanovercounty.gov">dhlee@hanovercounty.gov</a>

Cc: Martin, Gregory R. <grmartin@hanovercounty.gov>; Reaves, Stacy G. <sgreaves@hanovercounty.gov>

Subject: RE: Units 1226 and 21615

Importance: High

Don,

I've checked with Chesterfield Insurers regarding taking the trailer to MES – please have MES provide an estimate of repairs for the trailer and additionally I'll need an estimate for unit # 1226. Please update me ASAP as the claims representative will be contacting me tomorrow on 10/13/16.

#### Thank you,

Tim Blackwell Safety Specialist II 11375 N. Lakeridge Pkwy Ashland, VA 23005 (804) 365-7184 P (804) 365-3162 F

From: Lee, Donald H.

Sent: Wednesday, October 12, 2016 2:00 PM

To: Blackwell, Tim W.

Cc: Martin, Gregory R.; Reaves, Stacy G.

**Subject:** Units 1226 and 21615

Tim,

Fire/EMS trailer unit # 21615 was towed to Fleet Management, attached are photos that show the damaged area, a accident report will be completed tomorrow when the employee returns to work, the trailer had a tire blow out on it on 95S as it was being taken to a vendor, damage was also done to the truck (1226).

I'm attaching pictures, because of the damage caused to the air tanks we're recommending the trailer be taken to MES (Municipal Emergency Services) to inspect for safety. The air tanks were damaged as well as structural damage to the trailer.

The truck can be estimated on site.

From:

Blackwell, Tim W.

Sent:

Thursday, October 13, 2016 11:05 AM

To:

jennifer@chesterfieldinsurers.com

Subject:

FW: 21615

**Attachments:** 

IMG\_0099.JPG; ATT00001.txt

Importance:

High

Hi Jennifer,

Attached is the photo that goes with the recent claim that was just submitted regarding the trailer.

Thank you,


Tim Blackwell Safety Specialist II 11375 N. Lakeridge Pkwy Ashland, VA 23005 (804) 365-7184 P (804) 365-3162 F

----Original Message-----From: Lee, Donald H.

Sent: Thursday, October 13, 2016 11:03 AM

To: Blackwell, Tim W.

Subject: 21615



From:

Blackwell, Tim W.

Sent:

Thursday, October 13, 2016 11:06 AM

To:

jennifer@chesterfieldinsurers.com

Subject:

FW: 21615

**Attachments:** 

IMG\_0102.JPG; ATT00001.txt

Importance:

High

Jennifer,

This is a photo of the back bumper to the unit that the trailer struck. We are getting estimates put together for this claim. Can you see if Kelli Griswold will be handling at McNeil & Company.

Thank you,


Tim Blackwell Safety Specialist II 11375 N. Lakeridge Pkwy Ashland, VA 23005 (804) 365-7184 P (804) 365-3162 F

-----Original Message-----From: Lee, Donald H.

Sent: Thursday, October 13, 2016 11:04 AM

To: Blackwell, Tim W.

Subject: 21615



From:

Lee, Donald H.

Sent:

Thursday, October 13, 2016 7:53 AM

To:

Blackwell, Tim W.

Cc:

Smithson, Greg J.

Subject:

RE: Units 1226 and 21615

Did the trailer make contact with the passenger side rear bumper? Yes

What caused the trailer to become disconnected from the ball? When the tire blew out the excessive bouncing at 55 MPH caused the trailer to shear the safety pin, this allowed the trailer latch to release.

Was there a pin in the latch to prevent the trailer from becoming disconnected? Yes it was sheared off.

I'll get the photos to you in a few.

If there is anything else you need please contact me.

Thanks

#### Donald H. Lee

Fleet Manager County of Hanover General Services Department, Fleet Division W: (804) 365-6505 / C: (804) 339-5629 11375 Lakeridge Pkwy. Ashland, VA 23005

Hanover: People, Tradition and Spirit

Hanover County VA

From: Blackwell, Tim W.

Sent: Wednesday, October 12, 2016 4:20 PM
To: Lee, Donald H. <dhlee@hanovercounty.gov>

Cc: Martin, Gregory R. <grmartin@hanovercounty.gov>; Reaves, Stacy G. <sgreaves@hanovercounty.gov>

Subject: RE: Units 1226 and 21615

Don,

Greg and I walked in the back to take a look at the damage to the trailer and also the unit that was towing the trailer, can you get some photos of the wiring harness that is shredded and also damage to the rear bumper of the unit towing the trailer before it leaves the shop. Did the trailer make contact with the passenger side rear bumper? What caused the trailer to become disconnected from the ball? Was there a pin in the latch to prevent the trailer from becoming disconnected? These are questions that the insurance company are asking.

Thanks,

Tim

From: Lee, Donald H.

Sent: Wednesday, October 12, 2016 3:41 PM

To: Blackwell, Tim W.

**Cc:** Martin, Gregory R.; Reaves, Stacy G. **Subject:** RE: Units 1226 and 21615

Thanks I'll meet with you tomorrow to review the incident.

#### Donald H. Lee

Fleet Manager County of Hanover General Services Department, Fleet Division W: (804) 365-6505 / C: (804) 339-5629 11375 Lakeridge Pkwy. Ashland, VA 23005

Hanover: People, Tradition and Spirit

Hanover County VA

From: Blackwell, Tim W.

**Sent:** Wednesday, October 12, 2016 3:30 PM **To:** Lee, Donald H. <dhlee@hanovercounty.gov>

Cc: Martin, Gregory R. <grmartin@hanovercounty.gov>; Reaves, Stacy G. <sgreaves@hanovercounty.gov>

**Subject: RE: Units 1226 and 21615** 

Importance: High

Don,

I've checked with Chesterfield Insurers regarding taking the trailer to MES – please have MES provide an estimate of repairs for the trailer and additionally I'll need an estimate for unit # 1226. Please update me ASAP as the claims representative will be contacting me tomorrow on 10/13/16.

Thank you,

Tim Blackwell Safety Specialist II 11375 N. Lakeridge Pkwy Ashland, VA 23005 (804) 365-7184 P (804) 365-3162 F

From: Lee, Donald H.

Sent: Wednesday, October 12, 2016 2:00 PM

To: Blackwell, Tim W.

Cc: Martin, Gregory R.; Reaves, Stacy G.


**Subject:** Units 1226 and 21615

Tim,

Fire/EMS trailer unit # 21615 was towed to Fleet Management, attached are photos that show the damaged area, a accident report will be completed tomorrow when the employee returns to work, the trailer had a tire blow out on it on 95S as it was being taken to a vendor, damage was also done to the truck (1226).

I'm attaching pictures, because of the damage caused to the air tanks we're recommending the trailer be taken to MES (Municipal Emergency Services) to inspect for safety. The air tanks were damaged as well as structural damage to the trailer.

The truck can be estimated on site.



1	Faster - TS02 - ts02 - Remote Desktop Connection	
File Local Table Help		
Libraries IBM I Access for Windows		
☐ Equipment Inventory	ry - FASTER Win 6.2	LO X
Equipment Informa	ation::Company 001 THCGS-FLEET DIVISION	
Lee, Donald H. Mikrosoft Network    Equipment Number	Year     Make     Model     Shop     TSet     Licen       2005 ▼ CYGNUS     ▼ TRAILER     ▼ 01 ▼ EQ ▼ 12782       Parent Equipment     Class     Department	se 22L Print √
Computer System I Navigator	Component FAVB TRAILER, FIRE, VAN/B 321000 F  Serial Number FixAsset MG  1C9BF12245S929058	RE EMS GROUP FOR COMPA COUNTY GS-FLEET
Recycle Bin Motor Pool	Status	rder 0000110234
Master Billing	ŋ ] _웰 Notes   [ Acq/Disp ] 및 Vehicle Replacement 및 Search   및 Query ] 및 History ] Search	Q Componer 1 ▶
Company 001 ▼ Typ		arch Print 4
Control Panel  Acrobat Reader DC		
FASTER for Inquire equipment	t Completed : ACKNOWLEDGED	<mark>शटन्</mark> दः Upd

#### Donald H. Lee

Fleet Manager County of Hanover General Services Department, Fleet Division W: (804) 365-6505 / C: (804) 339-5629 11375 Lakeridge Pkwy. Ashland, VA 23005

Hanover: People, Tradition and Spirit Hanover County VA



**Employee Signature:** 

# Hanover County Injury/Incident Report, Part 1 AND SENT TO HUMAN RESOURCES DEPARTMENT

Type of Incident

Injury

# TO BE COMPLETED BY EMPLOYEE'S SUPERVISOR WITHIN 24 HOURS AFTER INCIDENT

Vehicle **Property** Human Resources Department VML **Near Miss** Member # 193 Phone: 804-365-6075 Fax: 804-365-6334 For moderate and severe injuries: For minor injuries: Provide First Aid; call 911 if needed **Provide First Aid** Send to panel physician, if needed or requested Secure the accident scene Accompany employee to medical care facility Supervisors must complete the Injury/Incident Form, Part 2, within 48 hours after an incident. FENERTY William First Name Yes Last Name MI **County Employee:** No **Social Security Number:** , =, . City **Street Address:** State Lip **Home Phone:** Work Phone: (804) 365-6501 Widowed **Marital Status:** Married Single Divorced Male Female Date of Incident (mm/dd/yy): 112 Time of Incident: //: 00 am pm HENTICO Co. South bound Location occurred: **Department:** General Services Fleet Div. Job Title: Employee's description of incident (Add sheet if needed): Traveling south bound I-95 just before the I-64 off ramp, had a tire blow out on Air Utility Trailer (veh. #21615). Trailer started to sway and it came unbooked from Tow Vehicle (veh. #1226). It did not have safety clairs Nature of injury/property damage (Add sheet if needed): come loose, they kept Tan. Ter attacked to Truck. DAMAGE dowe to Traiter Tunque Litch, satetychains, Traiter electrical vireing (plag), Right front lower Traiter Frame, Surge brake mechanism, lower Air Tanks on AT side File (breathing storage Tanks) will dame to Tow Veh- Rear bumper Were safeguards or safety equipment provided? Were safeguards or safety equipment being used? Yes No Name of witness(es): First Aid administered by: **Describe First Aid treatment: Supervisor Phone:** Supervisor Name (Print): **Supervisor Signature:** Date: PANEL OF PHYSICIANS INFORMATION GIVE TO EMPLOYEE AT TIME OF INCIDENT AND HAVE EMPLOYEE SIGN BELOW Panel of physicians provided? Yes No I understand that I must select a Panel Physician, if needed, from the list that has been given to me. If I decline to select a Panel Physician from the list approved by Hanover County, I understand that I may have to pay for any medical treatment or doctor's bills. I also understand that I may be denied Worker's Compensation for any absence based on a disability that is not certified by a Panel Physician. WILL NOT go to a physician at this time. WILL

9

Date (mm/dd/yy):



## Hanover County Injury/Incident Report, Part 2 TO BE COMPLETED BY EMPLOYEE'S SUPERVISOR AND SENT TO SAFETY AND RISK MANAGEMENT WITHIN 48 HOURS AFTER INCIDENT

	VIVIL	Tuman Resources Department	
	Member # 193	Phone: 804-365-6075 Fax: 804-365-6334	
The purpose of this	s Corrective Action Re	port is not to affix blame for the incident but to facilitate the identi	fication and
		ted to the incident and to help prevent reoccurrences.	
Injured Employ Date of Incident	1		
Date of Incident		10 / 12 / 20/6	
	COMPLET	TE DESCRIPTION OF INCIDENT	
Attach any supportin	ng information such as pi	ocedure followed, pictures, signed witness statements, reports, Sheriff's ve	hicle reports.
1 1 10 · 1	1 f. 11	Eur (be specific)? Herrico Co. I-95 south bour	rd lane.
A MAIT MILE	e betwee the -	2-69 off 14mp	
WHAT happe	<u>ened</u> ? Give detail	s, identify device, tool, machine, or equipment involved.	Identify
time of day and	weather condition	s if applicable. Right front rive un Air Utility	TAILER
(veh.# 21615	) had a blow u	ut. TON vehicle was Air UTility Fruck #5 (veh.	#1226)
Trailer starte	ed to summe very	, sadly, Trailer high come unhocked when safe	الماره ميك
broke, safer	to chains kent	railer Attached to Truck buts able to set Truck	K + Trail-
under exert	cal with a an	I stropped in skoulder office I. He when	Joh > 105
were Duch	red or damage	s if applicable. Right front rive on Air Utility in the Ton vehicle was Air Utility prock us (vehicle was Air Utility prock us (vehically, trailer high came unhooked when safe trailer attached to truck, has able to get Truck of stopped on shoulder of fread. No other of I had a weather conditions were good.	011,0,00
		- your weather - will think and the your	
WHAT factor	rs may have led	to the incident? A four hill as le a custo	· L ~ LT
holpelast	t realer was	to the incident? A down hill grade a curve	0
veryen ger	17471E7 SW179	ing more than . I it were on a time is that you	oax
ACTION DI	N / CODDECT	TIVE ACTION. WILL.	
reseasumence and	when will it he see	<b>TIVE ACTION:</b> What was, or is, being done to prevent	
reoccurrence and	when will it be con	npleted? Contact Safety / Risk Management for assistance,	if needed.
			rome .

From:

Jennifer <Jennifer@chesterfieldinsurers.com>

Sent:

Thursday, October 13, 2016 3:44 PM

To:

Blackwell, Tim W.

Subject:

RE: Message from "2503GSFSBP10"

Here is info on claim:

Claim is 13010120 and it is assigned to Craig Majka; ext. 577.

----Original Message----

From: Blackwell, Tim W. [mailto:twblackwell@hanovercounty.gov]

Sent: Thursday, October 13, 2016 12:21 PM

To: Jennifer

Subject: FW: Message from "2503GSFSBP10"

Importance: High

Jennifer,

Attached please find a copy of the internal incident report relating to the recent claim, please provide a copy to the claims representative that will be assigned to handle this claim.

Thank you,

Tim Blackwell Safety Specialist II 11375 N. Lakeridge Pkwy Ashland, VA 23005 (804) 365-7184 P (804) 365-3162 F

----Original Message----

From: fsfsb@ricohC2503.hanover.gov [mailto:fsfsb@ricohC2503.hanover.gov]

Sent: Thursday, October 13, 2016 12:15 PM

To: Blackwell, Tim W.

Subject: Message from "2503GSFSBP10"

This E-mail was sent from "2503GSFSBP10" (MP C2503).

Scan Date: 10.13.2016 12:14:48 (-0400) Queries to: fsfsb@ricohC2503.hanover.gov

From:

Lee, Donald H.

Sent:

Monday, October 17, 2016 10:22 AM

To: Cc: bear@mesfire.com

Subject:

Blackwell, Tim W. Air Utility Trailer

**Attachments:** 

20161012\_125342.jpg; 20161012\_125122.jpg; 20161012\_125139.jpg; 20161012\_

125250.jpg

#### Good morning Bear,

I've attached pictures of the damage the trailer sustained last week when it as involved in an accident, please review and advise.


Thanks,


#### Donald H. Lee


Fleet Manager County of Hanover General Services Department, Fleet Division W: (804) 365-6505 / C: (804) 339-5629 11375 Lakeridge Pkwy. Ashland, VA 23005


Hanover: People, Tradition and Spirit


Hanover County VA











From:

Blackwell, Tim W.

Sent:

Thursday, October 13, 2016 12:36 PM

To:

jennifer@chesterfieldinsurers.com

Subject:

FW: 21614

**Attachments:** 

IMG\_20161013\_110638839\_HDR.jpg; ATT00001.txt

Importance:

High

Jennifer,

This is a picture of the air tank underneath the trailer that got damaged once the tire blew out. Please make sure that the claims representaitive with McNeil & Company get this photo as well.

Thank you,


Tim Blackwell Safety Specialist II 11375 N. Lakeridge Pkwy Ashland, VA 23005 (804) 365-7184 P (804) 365-3162 F

-----Original Message-----From: Lee, Donald H.

Sent: Thursday, October 13, 2016 12:21 PM

To: Blackwell, Tim W.

Subject: 21614



# Invoice

# Robinson's Towing & Recovery, Inc.

P. O. Box 2735 8416 Old Richfood Road Mechanicsville, VA 23116 (804) 746-4937

Date	Invoice #	
10/12/2016	7461	

Bill To	
Hanover County General Services	
11375 NorthLake Ridge Parkway	
Ashland, VA 23005	

Ship To	
Hanover County General Services	
Phone 804-365-6505	
VENDOR: 214386	
Fax 804-365-6510	

P.O. No.	Terms	T		
21615				
Quantity	Item Code	Description	Rate	Amount
	Towing	Wrecker Service: reference	163.00	163.00
		Fire EMS Trailer Trailer # 21615 License # 127-822L VA Vin # 1C9BF122455929058		
		Located at: 95 South at exit 64		
,		Towed to: Hanover County General Services 11375 North Lakeridge Parkway Ashland, VA		•
		RECE Hanover County ( Vehicle #_ 入1615 Code: <u>Ч-100-</u> Ч3) (	Seneral Services	
		OCT 17	2016	
		Vendor #B Prepared by Approval	atch #	<u>-</u>
hank you for yo	our business.		Total	\$163.00

From:

Blackwell, Tim W.

Sent:

Monday, October 17, 2016 12:15 PM

To:

'Majka, Craig'

Cc:

Lee, Donald H.

Subject:

RE: claim # 13010120, The Board of County Supervisors of Hanover County, VA

Importance:

High

Craig,

Good Afternoon, It was a pleasure speaking with you this morning regarding Hanover county units # 21615 & # 1226 (Cygnus trailer & 1998 Ford). Thank you for providing an update, I'll also include the Hanover county fleet manager on this correspondence along with his contact information as it is best for the appraiser to work with the fleet manager regarding the repairs to both units.

Hanover county fleet manager:

Mr. Don Lee 11375 N. lakeridge Pkwy Ashland, VA 23005

(804) 365-6505 (office)

Thank you Craig and Don for working with the appraiser that McNeil & Company will be assigning. Please let me know if I can assist further with this claim.

Thank you,

Tim Blackwell Safety Specialist II 11375 N. Lakeridge Pkwy Ashland, VA 23005 (804) 365-7184 P (804) 365-3162 F

From: Majka, Craig [mailto:cmajka@mcneilandcompany.com]

Sent: Monday, October 17, 2016 12:04 PM

To: Blackwell, Tim W.

Subject: claim # 13010120, The Board of County Supervisors of Hanover County, VA

Tim, this email is to follow up on our conversation about the recently reported accident involving your 1998 Ford and Cygnus trailer. As we discussed, please forward your fleet maintenance contact and address info to me and I'll assign an appraiser to get right out and work with the County shop in the repair plan and pricing.

Once we have the figures I'll get you a proof of loss and payment(s).

#### Craig Majka

Sr. Claims Examiner



800-822-3747 x 577 main 607-428-1577 direct 607-756-5967 fax

#### mcneilandcompany.com

The information contained in this Electronic Mail Message is confidential information intended only for the use of the individual or entity named above, and may be privileged. If the reader of this message is not the intended recipient, or the employee, or agent responsible to deliver it to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by telephone (800-822-3747) and destroy the original message.