

**West Virginia Department of Health &  
Human Resources  
Berkeley County Health Department**

No image found with name:  
Berkeley.png. Image files  
needed to be generated.

**GENERAL SANITATION INSPECTION REPORT**

<b>Establishment Information</b>		
Facility Name Comfort Inn	Facility Type Motel/Hotel	
Licensee Name Aikens Corporation	Facility Telephone # 304	
Facility Address 1872 Edwin Miller Blvd Martinsburg , WV	Licensee Address ,	
<b>Inspection Information</b>		
Inspection Type Routine	Inspection Date 02/09/2018	Total Time Spent 1.75

**OPERATOR** - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

<b>Observed Violations</b>
<p><b>Total # 14</b> <b>Repeated # 0</b></p> <p><b>Room: 106</b>  <b>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.</b>  <b>OBSERVATION:</b> Floor behind drawer in-between beds needs cleaned</p> <p><b>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.</b>  <b>OBSERVATION:</b> Gasket on refrigerator needs replaced (torn)</p> <p>Room: 123  <b>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.</b>  <b>OBSERVATION:</b> Water shut-off valve cover in closet needs replaced/repaired. (loose)</p> <p>Room: 200  <b>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.</b>  <b>OBSERVATION:</b> Door stop needs repaired (pulled out of wall)</p> <p><b>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.</b>  <b>OBSERVATION:</b> Water line access in closet damaged with water and needs repaired</p> <p>Room: 216  <b>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.</b>  <b>OBSERVATION:</b> Inside of dishwasher needs cleaned</p>

**64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.**

**OBSERVATION:** Picture hanger needs removed from wall (no picture) Holes need sealed

Room: 304

**64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.**

**OBSERVATION:** Electrical outlet cover by bed needs replaced/repared (gap)

Room: 318

**64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.**

**OBSERVATION:** Grout missing in bathroom tiles behind door

Room: 406

**64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.**

**OBSERVATION:** Ceiling (over pictures) needs repaired

**64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.**

**OBSERVATION:** Caulking around tub/shower needs replaced (mold)

Room: 429

**64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.**

**OBSERVATION:** Lights in bathroom need repaired (falling out of ceiling) Visible gap.

Room: Laundry Room

**64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.**

**OBSERVATION:** Walls need repaired/Holes sealed

Room: Vending Machine Floor 3

**64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.**

**OBSERVATION:** Ceiling needs repaired

<b>Inspection Outcome</b>

<b>Comments</b>
406,429,318,304,200,216,106,123

Disclaimer

Person in Charge



**Amanda Runner**

Sanitarian



**Keith Allison**