



RipRap Failure Resolved With ScourStop Transition Mats

GENERAL INFORMATION

Property Owner: City of Delaware
Location: Executive Blvd.
Delaware, OH
Product Used: ScourStop
Quantity: 320 SF / 20 4x4 mats
Installed By: Delaware Maintenance Crew
Install Date: November 27, 2012
Contact: Greg Doubikin
Asst. Waste Water Manager

BACKGROUND

Reason for Product Use:
The riprap at the pipe outlet and headwall had failed and the water erosion had encroached in to a resident's backyard. The homeowner was unable to maintain their yard due to the excessive erosion. This was not only an erosion issue, but it was becoming a danger issue as well.

WHY THIS PRODUCT?

Product Details
ScourStop Transition Mats were chosen to provide a mechanical protection through impact resistance, tensile strength and permanent durability against the high erosion forces.

RESULTS

The ScourStop went in fast and efficiently. The area has been inundated with storm runoff and has held fast.

**B
E
F
O
R
E**

**A
F
T
E
R**



MEREDITH
BROTHERS, INC.