

**West Virginia Department of  
Health & Human Resources  
Berkeley County Health  
Department**



**GENERAL SANITATION INSPECTION REPORT**

| <b>Establishment Information</b>                        |                                   |                          |
|---|-----------------------------------|--------------------------|
| Facility Name<br>Hampton Inn-Foxcroft                   | Facility Type<br>Motel/Hotel      |                          |
| Licensee Name<br>Winchester Hospitality Inc             | Facility Telephone #<br>304       |                          |
| Facility Address<br>975 Foxcroft Ave<br>Martinsburg, WV | Licensee Address<br>              |                          |
| <b>Inspection Information</b>                           |                                   |                          |
| Inspection Type<br>Routine                              | Inspection Date<br>March 12, 2019 | Total Time Spent<br>1.75 |

**OPERATOR** - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

| <b>Observed Violations</b>   |
|--|
| <p><b>Total # 3</b><br/><b>Repeated # 0</b></p> <p><b>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.</b><br/><b>OBSERVATION:</b> Ice machines on 1st, 2nd, and 5th floor observed not clean in chutes. Ensure all water/ice contact surfaces are clean and sanitary condition.</p> <p>Room: 106<br/><b>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.</b><br/><b>OBSERVATION:</b> Room 106: Chip board of TV console in poor repair.</p> <p>Room: 1st Floor Water Fountain<br/><b>64-18-10.1 - The entire premises and its contents shall be maintained in good repair and in a clean and sanitary condition. Facilities and equipment shall be provided for this purpose.</b><br/><b>OBSERVATION:</b> 1st Floor Water Fountain: Water pressure low, does not go above guard, poor repair.</p> |

| <b>Inspection Outcome</b>                                     |
|---|
| Facility will be re-evaluated at the next routine inspection. |

| <b>Comments</b>   |
|---|
| Inspected Room 105, 106, 110, 209, 215, 310, 317, 400, 416, 500, 516, and 518. Inspected 1st floor and 3rd floor laundry, all ice machines, and 1st floor public restrooms and water fountains. Pest control once |

a month.

---

Disclaimer

Person in Charge

Sanitarian

**Signature On File**

**Robert RAD Deener**