

## DEL NORTE SENIOR CENTER WEATHERIZATION WORK ORDER

Ser	vTraq Job #:	3	313 Date A	ssigned:	5/1	0/2	019	Date to	be C	omple	ted:	5/24/2019
Clie	ent Name				Landle	ord/l	Prop	ery Owne	r Name	e: 🗹	Owne	er-Occupied
Joh	in Doe											
	dress				City, S					Client Phone		
1234 Main Street					Cresc	Crescent City, CA 95531				(707) 464-0000		
	✓ Initial Wx	Re-Wx	P	ermit:	N/A		City	County	F	Permit No.:		
cs	D Program	✓ LIHEA	P DC	DE PPL Eligible Yes No Electric WH								
Dw	elling Type:	Single	Family	y Mobile 1 Apartment MF < 5 units								
Hea	ater Type:	Baseboard	Ceiling	For	ced Air	4	Hea	at Pump	Space	Heater	Nor	n-Electric
		RE COUN		RIPTIO	N		Note	# Installed		Crew	/ Time	Billed \$
1	BLOWER DOOR TEST - PRE-TEST							TMO				
1	DUCT LEAKAC	DUCT LEAKAGE PRE-TEST WITH DUCT BLASTER				2			ТМО		5	
1	CARBON MONOXIDE ALARM							each				
1	SMOKE ALARM							each				
1	CAULKING, MOBILE HOME							lin. ft.				
15	COVER PLATE	COVER PLATE GASKETS							each			
2	DOOR REPAIR, EXTERIOR, ALL OTHER TYPE				PES		1		each			
1	DUCT REPAIR	JCT REPAIR AND REPLACEMENT					6		each			
1	FILTER REPLACEMENT, FURNACE						8		each			
1	HOT WATER FL	R FLOW RESTRICTOR, FAUCET RESTR			STRICT	OR	2		each			
1	LED NIGHT LI	GHTS							each			
1	LIMITED HOME REPAIR					3		ТМО				
1	MINOR ENVELOPE REPAIR						4		ТМО			
1	WATER HEATER BLANKET					7		each				
8	WATER HEAT	ER PIPE WI	RAP						lin. ft.			
1	WEATHERSTF	RIPPING, HI	NGED EXT	ERIOR	DOOR		1		each			
3	FLOOR FOUN	DATION VE	NTING				5		ТМО			
1	POWER STRIF	PS, TIER 2 A	ADVANCE	)					each			
	, , , , , , , , , , , , , , , , , , ,											
	-											
$\neg$												

	e performed or to	tion of work authorized above add Unit Costs to a job that						
the main body of the work	Oldon.							
1 H&S: repair/rigid weather	etrin/shoe kitchen t	to garage door (#2) before Blow	ver Door testing					
1. H&S: repair/rigid weatherstrip/shoe kitchen to garage door (#2) before Blower Door testing. Repair/snap-in weatherstrip front door (east facing; #1) after Blower Door testing.								
Ivehamenah-m meameremb	noni door (east la	onig, #1/ alter blower book test	9.					
2. Bathroom only.								
2. Danie Jin Jiny.	LULLANDE MARIONE REPLANTATION OF THE PROPERTY							
3. Line and seal return close	t with insulated du	ct board, plywood or sheet me	tal (according to					
CSD WIS Section 6, #24) walls and ceiling, approximately 81sqft of surface area. Remove and cap								
duct to laundry room (CSD FG; App, B, 6.1.3) do both before duct test. Add cover plate in bedroom of								
east facing wall, if needed w			I and the second					
cast lasing wan, ii lissaed w	gaonan							
4. Seal plumbing penetration	ns underneath the	home with closed cell foam or	caulking, then					
insulate with R-11 and seal belly board (CSD WIS Section 6 #44). Seal kitchen around kitchen								
exhaust vent pipe to ceiling.								
Division for pipe to coming.								
5. Add two 10"x14" to back	of the home (south	facing). Also, cut a 1'x4' hole i	n access and					
and staple 1/4" screen to ins		3,						
6 Renlace annrovimately 40	)' of flevible ducting	g 6", as needed (mostly main d	uct) Hang with					
straps (CSD WIS Section 6)		g o , as needed (mostly main d	acy, riang with					
Chaps (CCD VVIO CCCIIOII 0)	, before duct test.							
7. Earthquake strap water h	eater before wrapr	oing.						
a.tquano ottap water in	201010 WIUPP	····•9'						
8. 16"x20"x1"								
- 10 ALC A1								
Accessor Cianatura	Data	Mark Authorized	Data					
Assessor Signature	Date	Work Authorized	Date					
	CONTRACTO	OR'S CERTIFICATION						
Legrify that the work author		order has been completed acco	rding to applicable state					
_	-	tandards and materials specific						
weatherization program.	i ilie regulations, s	tandarus and materiais specific	Janona of the					
weathenzation program.								
Contractor Signature		Date						