PWD DEPARTMENT

Office of the

Assistant Executive Engineer

P.W. Dept, Sub-Division Hubli.

Email ID: aeeowdhbl@gmail.com

S.No.: PWD/DB/2020-21/1254

Phone No.: 0836-2352210

Date: 15/02/2021

To.

Principal

J K Education Society's

Smt. Drakshayani Kalyanshettar

Public School (CBSE)

Shakti Colony, Near Adhyapak Nagar

Hubli- 580032.

Respected Sir/ Madam,

Sub 1: To Issue Certificate for the Building Safety.

Reference: Your application No. DK/17/2020-21, Dated: 15/12/2020

With reference to the above subject, Principal JK Education Society's Smt. Drakshayani Kalyanshettar Public School (CBSE), Shakti Colony Near Adhyapak Nagar Hubli- 580032 have requested for the Structural Stability Certificate on 20/01/2021. B. M. Associates Architectural & Structural Consultants & Builders, Hubli had inspected the school on 02/02/2021 and the building is having RCC framed structure of Basement, Ground Floor, First Floor, Second Floor & Third Floor. Hence, the existing structure is safe enough to take the overcoming loads and to

A English Medium School.

Your's faithfully

Assistant Engineer **PWD Department** Hubli

AFFEDEVATE

atm IM Ronad Advocate Hubli I townslated above document from Kannada to English and English

SULEMNLY AFFIRMED BEFORE MI

26 APR 2



Office of the Assistant Executive Engineer P.W Dept, Sub-Division Hubli. ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನೀಯರವರ ಕಛೇರಿ ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ಉಪವಿಭಾಗ, ಹುಬ್ಬಳ

Email.ID: aeepwdhbl@gmail.com

ದೂರವಾಣ್ ಸಂಖ್ಯೆ: 0836-2352210

ಕ್ರಸಂ:ಸಕಾವಂಹು/ಲೋವ/ಡಿಬ/2020-21/

ದಿನಾಂಕ: 15- 42 - 242)

Principal

J K Education Society's
Smt Drakshayani Kalyanshettar
Public School (CBSE),
Shakti colony Near Adhyapak
Nagar Hubli-580032

ಮಾನ್ಯರೇ,

ವಿಷಯ 1-ಕಟ್ಟಡ ಸದ್ಯಡ ಪ್ರಮಾಣ ಪತ್ರ ಕೊಡುವ ಕುರಿತು.

ಉಲ್ಲೇಖ 1-ತಮ್ಮ ಅರ್ಜಿಯ ಸಂ:ಡಿಕೆ/17/2020-21 ದಿನಾಂಕ:15-12-2020

ಮೇಲಿನ ವಿಷಯ ಹಾಗೂ ಉಲ್ಲೇಖಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, Principal J K Education Society's Smt Drakshayani Kalyanshettar Public School (CBSE), Shakti colony Near Adhyapak Nagar Hubli-580032 ಇವರ ಕಟ್ಟಡದ ಸದ್ಯಡತೆಯ ಕುರಿತು ಉಲ್ಲೇಖದ ಪತ್ರದಲ್ಲಿ ವಿನಂತಿಸಿದ್ದು, ಸದರ ಕಟ್ಟಡದ ಸದ್ಯಡತೆ ಕುರಿತಂತೆ ದಿನಾಂಕ: 20-01-2021 ರ ಪತ್ರದಲ್ಲಿ B. M. Associates Architectural & Structural Consultants & Builders Hubli ಇವರಿಂದ ಕಟ್ಟಡದ ಸದ್ಯಡತೆಯ ಬಗ್ಗೆ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಹೊರೈಸಿರುತ್ತಾರೆ. ಕಟ್ಟಡವನ್ನು ದಿನಾಂಕ:-02-02-2021 ರಂದು ಪರಿವೀಕ್ಷಣೆ ಮಾಡಲಾಗಿದೆ. ಸದರ ಕಟ್ಟಡದ ನೆಲ ಮಾಳಿಗೆ, ನೆಲ ಮಹಡಿ, ಒಂದನೇ ಮಹಡಿ, ಎರಡನೇ ಮಹಡಿ ಹಾಗೂ 3ನೇ ಮಹಡಿಗಳಿದ್ದು, ಸದರ ಕಟ್ಟಡದಲ್ಲಿ ಇಂಗ್ಲೀಷ ಮಾಧ್ಯಮ ಶಾಲೆ ನಡೆಸಲು ಯೋಗ್ಯವಿರುತ್ತದೆ ಎಂದು ಈ ಮೂಲಕ ದೃಡಿಕರಿಸಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜನೀಯರರು, ಮೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ಉಪವಿಧಾಗ, ಹುಬ್ಬಳ್ಳಿ.

CONTROL OF THE PROPERTY AND UNION

Ref No

Date 20/01/2021

STRUCTURAL STABILITY CERTIFICATE

This is to certify that the existing structure In R.S. No. 179/1A/2, Shakti colony near Adhyapak Nagar, Hubli of J. K. Education Society's Smt. Drakshayani Kalyanshettar Public School has been inspected by me on 19/01/2021 and the building is having RCC framed structure of Basement, Ground floor, First floor, Second floor and Third floor. The structure is found to be safe/strong in accordance with the requirements and provision of the National Building Code and necessary IS Code of practice (governing standards to resist the Dead Loads, Live Loads etc.) Hence, the Existing Structure is safe enough to take the overcoming loads.

Structural Engineer

(B. Mahesh)

