

## **Appendix B**

### **Photo Log**

**Client's Name:**  
Iron County Forest and Parks Department

**Site Location:**  
Saxon Harbor Campground

**Project No.**  
17I007

**Photo No.** 1

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Saxon Harbor



**Photo No.** 2

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Saxon Harbor



**Client's Name:**  
Iron County Forest and Parks Department

**Site Location:**  
Saxon Harbor Campground

**Project No.**  
17I007

**Photo No.** 3

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Sediment and storm debris build up.



**Photo No.** 4

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Saxon Harbor



**Client's Name:**  
Iron County Forest and Parks Department

**Site Location:**  
Saxon Harbor Campground

**Project No.**  
17I007

**Photo No.** 5  
**Date:** 5/25/17  
**Photo Taken By:** SDG  
**Description:** Sediment build up within creek.



**Photo No.** 6  
**Date:** 5/25/17  
**Photo Taken By:** SDG  
**Description:** Sediment build up within creek.



**Client's Name:**  
Iron County Forest and Parks Department

**Site Location:**  
Saxon Harbor Campground

**Project No.**  
17I007

**Photo No.** 7

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Sediment build up within creek.



**Photo No.** 8

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Sediment build up within creek.



**Client's Name:**  
Iron County Forest and Parks Department

**Site Location:**  
Saxon Harbor Campground

**Project No.**  
17I007

**Photo No.** 9

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Storm damage to abutments of CTH A Bridge.



**Photo No.** 10

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Storm damage to abutments of CTH A Bridge.



**Client's Name:**  
Iron County Forest and Parks Department

**Site Location:**  
Saxon Harbor Campground

**Project No.**  
17I007

**Photo No.** 11

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Storm damage to abutments of CTH A Bridge.



**Photo No.** 12

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Storm damage to abutments of CTH A Bridge.



**Client's Name:**  
Iron County Forest and Parks Department

**Site Location:**  
Saxon Harbor Campground

**Project No.**  
17I007

**Photo No.** 13

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Storm erosion of CTH A road.



**Photo No.** 14

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Storm erosion of CTH A road.



**Client's Name:**  
Iron County Forest and Parks Department

**Site Location:**  
Saxon Harbor Campground

**Project No.**  
17I007

**Photo No.** 15

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Alternative area for Campground relocation



**Photo No.** 16

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Alternative area for Campground relocation



**Client's Name:**  
Iron County Forest and Parks Department

**Site Location:**  
Saxon Harbor Campground

**Project No.**  
17I007

**Photo No.** 17  
**Date:** 5/25/17  
**Photo Taken By:** SDG  
**Description:** Alternative area for Campground relocation



**Photo No.** 18  
**Date:** 5/25/17  
**Photo Taken By:** SDG  
**Description:** Timber build up within Saxon Harbor from storm



**Client's Name:**  
Iron County Forest and Parks Department

**Site Location:**  
Saxon Harbor Campground

**Project No.**  
17I007

**Photo No.** 19

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Creek shoreline erosion from storm event.



**Photo No.** 20

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Creek shoreline erosion from storm event.



**Client's Name:**  
Iron County Forest and Parks Department

**Site Location:**  
Saxon Harbor Campground

**Project No.**  
17I007

**Photo No.** 21

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Alternative area for Campground relocation



**Photo No.** 22

**Date:** 5/25/17

**Photo Taken By:** SDG

**Description:** Saxon Harbor

