

KIRILA FIRE TRAINING FACILITIES, INC.

DESCRIPTION OF SERVICES

SBBI STRUCTURAL BURN BUILDING ANNUAL INSPECTION

This service has been developed to provide inspections to live fire training structures by a licensed professional engineer with live fire training structure experience and expertise.

This service is to directly meet the requirements of NFPA 1403 Standard on Live Fire Training Evolutions, 2007 Edition, Chapter 5 Gas Fired Live Fire Training Structures, Paragraph 5.2.2.2 and 5.2.2.3 and Chapter 6, Non-Gas-Fired Live Fire Training Structures, Paragraph 6.2.2.2.

This service will include a site visit and a complete evaluation of the structural integrity of the subject facility.

A debriefing will be provided to the end user, and a full and comprehensive report will be generated of the findings.