Seaside Marine Surveyors LLC

Gary Friend, MMS, SA P.O.Box 25, Port Jefferson Station, N.Y. 11776 Phone. 631-403-0437 USSA, SAMS www.SeasideMarineSurveyors.com

Compression Test

<u>Client Name</u>: Mr. Smith <u>Client Address</u>: 123 Street, Any town, N.Y. 11333 <u>Client Phone Number(s)</u>: 717-111-2222 <u>Year/Make/Model of Vessel</u>: 1992 25 Stamas W/A cuddy <u>Vessel Name</u>: My Yacht <u>Hull Identification Number</u>: STA123B456C792 <u>Documentation / Registration #</u>: NY-1111-AA <u>Propulsion Type</u>: Twin Suzuki outboards <u>Year, Make, Model</u>: 1992 Suzuki 200 <u>Serial Number</u>: 123456789 <u>Hours</u>: P-765, S-772

Port Engine	Left Bank	Right Bank	Starboard Engine	Left Bank	Right Bank
# 1 cylinder	125	123	# 1 cylinder	126	125
# 2 cylinder	123	123	# 2 cylinder	123	124
# 3 cylinder	125	125	# 3 cylinder	123	124
# 4 cylinder			# 4 cylinder		
# 5 cylinder			# 5 cylinder		
# 6 cylinder			# 6 cylinder		

Cylinders are numbered as per the manufacturer's specifications of the engines.

Comments: The compression test results need to fall within 15 psi of the highest and lowest cylinder to be considered in good condition. These engines fall within these specifications and do not indicate any abnormal or excessive cylinder or ring wear in any particular cylinder.