


SEE ADDENDUM FOR ADDITIONAL/CORRECTED INFORMATION

Ohio Historic Preservation Office
1985 Veima Avenue
Columbus, Ohio 43211
614 456-1500



OHIO HISTORIC INVENTORY

1. No. ERI-1569		4. Present Name(s) Harold Smith House		1. No. ERI-1569
2. County ERIE		5. Other Name(s) William C. Schlesselman Residence		
3. Location of Negatives O.H.S.		16. Thematic Category agriculture, Commerce		4. Present Name(s) Harold Smith Residence
6. Specific Location East side of Division street, 4th house from Town Hall, north to Chapel St.		17. Date(s) or Period 1937		
7. City or Town If Rural, Township & Vicinity Kelleys Island, Ohio		18. Style or Design Tudor		4. Present Name(s) Harold Smith Residence
8. Site Plan with North Arrow 		19. Architect or Engineer Godfrey Schock		
9. U.T.M. Reference Zone Easting Northing 117 357480 4606100		20. Contractor or Builder Godfrey Schock		4. Present Name(s) Harold Smith Residence
10. Site <input type="checkbox"/> Building <input checked="" type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/>		21. Original Use, if apparent Residence		
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		22. Present Use Residence		4. Present Name(s) Harold Smith Residence
12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>		
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		24. Owner's Name & Address, if known Harold Smith 7160 Laura Lee Ln. Seven Hills, Ohio 44131		4. Present Name(s) Harold Smith Residence
14. District Potent? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		
15. Name of Established District N/A		26. Local Contact Person or Organization Kevin Pape-KI Histor. Survey		4. Present Name(s) Harold Smith Residence
		27. Other Surveys in Which Included N/A		
42. Further Description of Important Features (Continue on reverse if necessary) The facade of this side-gabled house is dominated by a steeply pitched cross-gable that features a central, exterior chimney. The glacial-erratic wall cladding is trimmed with dressed limestone quoins at all corners, door and window surrounds, and on the chimney. Windows are a mixture of double-sash and casement types. Doors and windows are treated with plain lap sills and flat arch limestone		43. History and Significance This and an identical house to the north are two of three houses on the island built of glacial erratics, the third being a summer cottage (ERI-1646). All three were the work of the same artisan, Godfrey Schock, the island stone mason who also built many chimneys and fireplaces, porches using this same media. It was built for William C. Schlesselman in 1937 on the southern half of a one acre plot of old vineyard which had probably been part		5. Other Name(s) William Schlesselman Hs.
44. Description of Environment and Outbuildings The house is located on the fringe of the island business district. Overgrown fields held by the Ohio Department of Natural Resources lie to the east.		45. Sources of Information Census Records, Erie County 1909 Platt Map, Kelleys Island Mary Schock F. Wm. Pape		
		46. Prepared by Betty Pape Kate Boker & Kevin Pape		5. Other Name(s) William Schlesselman Hs.
		47. Organization KI.Planning Commission		
		48. Date 9/85		5. Other Name(s) William Schlesselman Hs.
		49. Revision Date(s)		

