

East Feliciana Rural Water System

Street Address	City	State	Zip	Unique Service Line ID	Latitude (Recommended)	Longitude (Recommended)	Additional Location Identifier (e.g., subdivision, building number, building name, etc.)	System-Owned Service Line Material	Basis of Material Classification (System)	Was Service Line Material Ever Previously Lead?	Service Line Connector (i.e., Short connector used to connect service line to main. Under the proposed EPA LCR, connector materials will likely be a required inventory element. Including now will reduce future burden.)	Service Line Installation Date (System)	Comments (System-Owned Portion)	Customer-Owned Service Line Material	Basis of Material Classification (Customer)
8384 HIGHLAND DRIVE	ETHEL	LA	70730	90-0187				Non-Lead - Plastic	Visual Inspection (for example, visual confirmation at meter pit)	No	Never lead	Post lead ban of 1988		Non-Lead - Material Unknown	Visual Inspection (for example, visual confirmation at meter pit)
8016 PINE STREET	ETHEL	LA	70730	90-0188				Non-Lead - Plastic	Visual Inspection (for example, visual confirmation at meter pit)	No	Never lead	Post lead ban of 1988		Non-Lead - Material Unknown	Visual Inspection (for example, visual confirmation at meter pit)
8704 LAKESHORE DRIVE	ETHEL	LA	70730	90-0189				Non-Lead - Plastic	Visual Inspection (for example, visual confirmation at meter pit)	No	Never lead	Post lead ban of 1988		Non-Lead - Material Unknown	Visual Inspection (for example, visual confirmation at meter pit)
7960 HYBISCUS DRIVE	ETHEL	LA	70730	90-0190				Non-Lead - Plastic	Visual Inspection (for example, visual confirmation at meter pit)	No	Never lead	Post lead ban of 1988		Non-Lead - Material Unknown	Visual Inspection (for example, visual confirmation at meter pit)
7819 PINE STREET	ETHEL	LA	70730	90-0191				Non-Lead - Plastic	Visual Inspection (for example, visual confirmation at meter pit)	No	Never lead	Post lead ban of 1988		Non-Lead - Material Unknown	Visual Inspection (for example, visual confirmation at meter pit)
8036 RALEIGH DRIVE	ETHEL	LA	70730	90-0192				Non-Lead - Plastic	Visual Inspection (for example, visual confirmation at meter pit)	No	Never lead	Post lead ban of 1988		Non-Lead - Material Unknown	Visual Inspection (for example, visual confirmation at meter pit)
8413 MILLER DRIVE	ETHEL	LA	70730	90-0193				Non-Lead - Plastic	Visual Inspection (for example, visual confirmation at meter pit)	No	Never lead	Post lead ban of 1988		Non-Lead - Material Unknown	Visual Inspection (for example, visual confirmation at meter pit)
8145 WEST LAKESHORE DRIVE	ETHEL	LA	70730	90-0194				Non-Lead - Plastic	Visual Inspection (for example, visual confirmation at meter pit)	No	Never lead	Post lead ban of 1988		Non-Lead - Material Unknown	Visual Inspection (for example, visual confirmation at meter pit)
8130 WEST LAKESHORE DRIVE	ETHEL	LA	70730	90-0195				Non-Lead - Plastic	Visual Inspection (for example, visual confirmation at meter pit)	No	Never lead	Post lead ban of 1988		Non-Lead - Material Unknown	Visual Inspection (for example, visual confirmation at meter pit)
8136 WEST LAKESHORE DRIVE	ETHEL	LA	70730	90-0196				Non-Lead - Plastic	Visual Inspection (for example, visual confirmation at meter pit)	No	Never lead	Post lead ban of 1988		Non-Lead - Material Unknown	Visual Inspection (for example, visual confirmation at meter pit)
7899 PINE STREET	ETHEL	LA	70730	90-0197				Non-Lead - Plastic	Visual Inspection (for example, visual confirmation at meter pit)	No	Never lead	Post lead ban of 1988		Non-Lead - Material Unknown	Visual Inspection (for example, visual confirmation at meter pit)