

Log Housing In The Bush

LOG Part V

This part will serve as repository for displaying images of a place that has been occupied for twenty years, also the wear and tear, or durability, of log construction. Also, will be included, as a sort of addendum, some images that were not included in the other parts.

Some additional commentary would seem to follow as part of the included imagery. The self-evident will speak for itself. Plus any additional thoughts regarding Log Housing In The Bush.



Log Housing In The Bush



Shaping The Wall Timbers And Cross Beams To Conform To The Roof Line Set At The Width Of A 2 x 4 On End (Above The Top Wall Log)



looking East (South Side)


Top Logs Shaped To Roof Line Using Alaska Mill



Looking East (North Side)



Log Housing In The Bush



Log Housing In The Bush

Beginnings Of Woodshed



Located ~15 ft. Diagonally From House



Constructed From Log House Remnants

Log Housing In The Bush



Finished Woodshed



Log Housing In The Bush



Log Housing In The Bush




Log Housing In The Bush



Log Housing In The Bush



Log Housing In The Bush



Log Housing In The Bush



Log Housing In The Bush

*W
o
o
d
s
h
e
d

1

M
o
s
t
l
y

F
u
l
l*



*W
o
o
d
s
h
e
d

2

F
u
l
l*

Log Housing In The Bush

Garden Fallow Year



Fall Rye Springtime



Buckwheat Early Summer

Log Housing In The Bush



Southwesterly Blows One Down



Log Housing In The Bush

*Back Porch Freshly Painted
North Side (Looking West)*



*Back Porch Glazed
Looking East*

Log Housing In The Bush



Log Housing In The Bush



Northwest Corner (facing West) Logwork after 20 Years

Log Housing In The Bush



Log Housing In The Bush



Log Housing In The Bush

