



1 Bedroom / 1 Bath



MODEL "I"



LIMITED COMMON ELEMENTS

1 Bedroom / 1 Bath



MODEL "II"



LIMITED COMMON ELEMENTS

1 Bedroom / 1 Bath



MODEL "III"



LIMITED COMMON ELEMENTS

1 Bedroom / 1 Bath


MODEL "V"



LIMITED COMMON ELEMENTS

1 Bedroom / 1 Bath


MODEL "IV"



LIMITED COMMON ELEMENTS



2 Bedroom / 1 Bath

MODEL "VI"



2 Bedroom / 1 Bath


MODEL "VII"



LIMITED COMMON ELEMENTS

2 Bedroom / 2 Bath

MODEL "VIII"




LIMITED COMMON ELEMENTS



2 Bedroom / 2 Bath



MODEL "IX"



LIMITED COMMON ELEMENTS

3 Bedroom / 2 Bath

MODEL "X"



LIMITED COMMON ELEMENTS



GARY B. CASTEL SURVEYING, INC.

LAND SURVEYORS

1111 S.W. 11TH AVENUE, SUITE 1000, MIAMI, FLORIDA 33136

3 Bedroom / 2 Bath

MODEL "XI"




LIMITED COMMON ELEMENTS



Townhouse

MODEL "XII"

First Floor



Second Floor




LIMITED COMMON ELEMENTS


Townhouse

MODEL "XIII"

Second Floor



First Floor



LIMITED COMMON ELEMENTS