

*Aquatic Environmental Services of AQUA DOC*

**Lake Service Report**

Property Name: Mirror Lake AES Representative: Greg B.  
Service Date: 5/20/20 Service Time: 9:09 a.m. –  
10:36a.m.

Water Temperature: 68 Degrees  
Visibility: 30"

Water Level Full Pool

Trash Collected: Abundant

Weather Conditions Cloudy

Outlet Debris Cleared: Clear

Lake Dye Applied: N/A Amount Applied: N/A

Pond Fertilizer Applied: N/A Amount Applied: N/A

Fish Feeders Checked: N/A Amount Applied: N/A

Aquatic Vegetation Identified: Pennywort

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, man - made debris removed, plankton in full bloom

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in great condition. We removed a large amount of man-made debris from the shore line of the lake. Good fish activity noted, pennywort found but no at a nuisance level, no algae at this time, water green due to planktonic bloom.

*Aquatic Environmental Services of AQUA DOC*



Figure 1

*Aquatic Environmental Services of AQUA DOC*



Picture 2

*Aquatic Environmental Services of AQUA DOC*



Picture 3

**AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC**  
8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230  
Fax: 770-737-5135 Email: [aquadocga@gmail.com](mailto:aquadocga@gmail.com) Website: [www.aquadocinc.com](http://www.aquadocinc.com)

*Aquatic Environmental Services of AQUA DOC*



**AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC**  
8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230  
Fax: 770-737-5135 Email: [aquadocga@gmail.com](mailto:aquadocga@gmail.com) Website: [www.aquadocinc.com](http://www.aquadocinc.com)