

## **2017 URSCC Annual Building and Grounds**

Carriage House perimeter beams and foundation

Debris cleanup, move lumber to garage, clean carriage house (Bill Vaughn)

Iconic Pine tree next to carriage house removed

Upstairs landing, hall, 1st floor tower – patch, prime and paint

Bonine floor repair and refinishing (Corey – parlor; Nichols Flooring)

Scrape bark from Carriage House beams

Have Carriage House sprayed for post beetles twice

Tower flashing pressure wash, prime and painting

Glass block window removed to be replaced with window to match house

West wall brick repair ongoing

Ongoing maintenance – p.w ramp, window cleaning, spring cleanup, gardens