

OHIO HISTORIC INVENTORY

1. No. ERI-1542		4. Present Name(s) Richard and Scotty Zitte		ERI-1542																						
2. County ERIE		5. Other Name(s) Quarry Store Offices																								
3. Location of Negatives U.H.S.																										
6. Specific Location South side of Bookerman Rd. opposite intersection of dump Rd. with Bookerman		16. Thematic Category Manufacturing		2. County ERIE																						
7. City or Town If Rural, Township & Vicinity Kelleys Island, Ohio		17. Date(s) or Period c1900																								
8. Site Plan with North Arrow		18. Style or Design Vernacular		4. Present Name(s) Richard and Scotty Zitte																						
		19. Architect or Engineer -																								
9. U.T.M. Reference <table border="1"> <tr> <td>17</td> <td>3</td> <td>5</td> <td>68</td> <td>0</td> <td>0</td> <td>46</td> <td>0</td> <td>7</td> <td>16</td> <td>0</td> </tr> <tr> <td colspan="6">Easting</td> <td colspan="5">Northing</td> </tr> </table>		17	3	5	68	0	0	46	0	7	16	0	Easting						Northing					20. Contractor or Builder -		5. Other Name(s) Quarry Store Offices
17	3	5	68	0	0	46	0	7	16	0																
Easting						Northing																				
10. Site Building <input type="checkbox"/> Structure <input type="checkbox"/> Object <input checked="" type="checkbox"/>		21. Original Use, if apparent Quarry Office																								
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		22. Present Use Residence		28. No. of Stories 1																						
12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>																								
13. Part of Estab. Yes <input type="checkbox"/> Hist. Dist.? No <input checked="" type="checkbox"/>		24. Owner's Name & Address, if known Richard & Scotty Zitte 1408 N. Meade St. Appleton, Wisc. 54911		29. Basement? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>																						
14. District Potent? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>																								
15. Name of Established District N/A		26. Local Contact Person or Organization Kevin Pape: KI.Hist.Survey		30. Foundation Material limestone rubble																						
		27. Other Surveys in Which Included N/A																								
42. Further Description of Important Features (Continue on reverse if necessary) This front-gabled building has simple lines and stark detailing limited to narrow frieze and end boards. Windows are 2/2 and, except for the gable end, have vertical board shutters. Front entrance is protected by shed-roofed canopy supported by sawn knee braces. Side entrance is located in rear gabled addition, built continuously with the roof line. The rear addition contains a brick chimney on the gable slope and an external brick flue stack.		31. Wall Construction Wood frame		32. Roof Type & Material Gable/asph. shingle																						
43. History and Significance This building originally stood on the shore of the west bay, just south of the limestone loading dock (ERI-1729), and was used by the Kelley Island Lime & Transport Co. c 1900. After its West Bay store and office (ERI-1547) burned in 1921, Superintendent Guerin planned a new and larger replacement, but work was becoming		33. No. of Bays Front Side																								
44. Description of Environment and Outbuildings House is situated near intersection of roads leading to south shore and entrance to KIL&T Co. West Bay shops (See Er337). Foundation of Reinheimer quarry store, which burned Dec. 25, 1919, is just west of the house. It sits on a mown lot and has exterior cistern.		34. Wall Treatment ship-lapp		35. Plan Shape Rec.																						
Sources of Information Oral Hist: Joseph Feyedelem Ray Feyedelem Barbara Coleman		36. Changes (Explain in #42) Addition <input checked="" type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved <input type="checkbox"/>																								
		37. Condition Interior Fair Exterior Fair		38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>																						
		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>																								
		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		41. Distance from and Frontage on Road 15																						
		46. Prepared by Kevin Pape Barbara Coleman																								
		47. Organization KI.Planning Commis		48. Date 9/85																						
		49. Revision Date(s)																								



50. House Type No.

Code No. _____ Name _____

51. Historic Outbuildings and Dependencies

Barn Type(s)

Code No. _____ Type _____

Corn Crib or Shed Silo Summer Kitchen Smoke House, Spring House or Ice House Privy Carriage House

Other _____

52. Archaeological Site on Property?

Yes
 No

Basis for Information

Owner Collection
 Above Ground Earthworks or Mound
 Cultural Materials Noted OAI No. _____

53. Farmstead Plan



54. Photo

Roll No. 21 Picture No(s). 23-24

42. (Cont'd)

43. (Cont'd.)

slack and funds were not approved by the company's headquarters. So, as an inexpensive substitute this building was moved up to its present site just east of the old office foundations (still visible), and used as the company office until c 1939.