

	16177	HAIRSTON	JCL	
EGAL DESCRIPTION LL SW 1/4 OF SW 1/4, SECTION 11, TOWNSHIP 19 SOUTH, RANGE 2 EAST, LYING NW OF IGHWAY 231, SOUTHWEST OF NORTH LINE OF VACATED 6th STREET AND NORTHEAST F CENTRAL OF GEORGIA RAILROAD. XCEPT PROPERTY IN INST. NO. 1996-24936. HE ABOVE DESCRIBED PROPERTY ALSO DESCRIBED AS BEING ALL OF BLOCKS 26, 27, 2 AND 33, CRUME'S MAP OF THE TOWN OF VINCENT. XCEPT PROPERTY DESCRIBED IN INST. NO.1996-24936. eing more particularly described as follows:	PROJECT No:	VER:	CHECKED BY:	GHWAY 25, VINCENT, AL
OMMENCING at the southwest corner of the southwest quarter of the southwest quarter of section 11, ownship 19 South, Range 2 East, Shelby County, Alabama, thence North 00° 31' 09" East for a istance of 257.16 feet to A 1/2" rebar on the northern rail-road right of way, said point being the OINT OF BEGINNING of the parcel herein described; thence leaving said right of way North 00° 31' 9 West for a distance of 583.21 feet a rebar; thence South 70° 59' 40" EAST for a distance of 803.92 et to a 1/2" rebar on the northwestern right of way of Shelby County Highway 25 (AKA State ighway 231); thence along said right of way South 19° 59' 14" West for a distance of 474.75 feet to a 4" crimp pipe; thence leaving said right of way North 68° 46' 42" West for a distance of 110.00 feet to 1/2" rebar; thence South 19° 59' 14" West for a distance of 79.37 feet to a 1/2" rebar; thence North 70° 0' 46" West for a distance 15.00 feet to a 1/2" rebar; thence South 19° 56' 14" West for a distance of 8.12 feet; thence South 88° 35' 32" West for a distance of 246.44 feet to a 1/2" rebar on the ortheastern rail road right of way; thence along said right of way North 35° 22' 44" West for a distance f 309.91 feet to the POINT OF BEGINNING of the parcel herein described. Said parcel containing 0.02 Acres, more or less.	1"=50' PR	12/09/2016 OWNER:	JKT CHI	HIGH
JRVEYOR'S NOTES	SCALE:	DATE:	DRAWN BY:	ADDRESS:
 Type of Survey - This is a Boundary Survey of the "Subject Property," made on the ground under the pervision of an Alabama Registered Land Surveyor. This survey was conducted for the purpose of a Boundary rvey only, and is not intended to delineate the regulatory jurisdiction of any federal, state, regional or local ency, board, commission or other similar entity. The "Subject Property" refers to the property described hereon. Bearings and Datum - Bearings are based on "Grid North," in accordance with the State Plane Coordinates for e State of Alabama, Zone West, from the North American Datum of 1983 (NAD83), Vertical Datum: NAVD 88. asite horizontal control was established through GPS observations, utilizing National Geodetic Survey (NGS) ntrol monuments and the ALDOT COORS network. A railroad spike was found in the north face of an existing lity pole near an asphalt drive having an elevation of 500.27'. Overhead and Subsurface Features – Subsurface features such as underground utilities, septic tanks, derground encroachments, underground mines, and/or subsurface building foundations were not measured or cated as a part of this survey. Notice is hereby given that the appropriate utility location service (e.g. "One Call," all 811," or "Call-Before-You-Dig"), should be notified forty-eight (48) hours in advance of any excavation at is site. Cemeteries, Trees and Significant Observations - This surveyor did not observe visible evidence of burial to under our card as the subject property and no information as to the existence of such has been provided to for the surveyor of the surveyor of the surveyor and no information as to the existence of such has been provided to for the surveyor of the survey of the surveyor of the survey of the survey of the survey of the surveyor did not observe visible evidence o	BOUNDARY SURVEY	PID 07 1 11 3 301 001.000	SHELBY COUNTY,	ALABAMA
 is surveyor. Trees and shrubs smaller than 15" DBH (diameter at breast height) not located. Trees are 15"-24" 3H unless otherwise noted. The property has significant overgrowth, and as a result there may be existing surface uctures that are not located on this survey (concrete patio, walkways, ect.) Boundary Issues - All property corners were found or set as per a result of this survey. Gas lines were located by s company representative, no easement documents were ever presented to surveyor. Title Report - This survey was conducted without the benefit of an abstract of title, title report, or title opinion, erefore, there may be other easements, rights-of-way, setback lines, agreements, reservations, restrictions, or other nilar matters of public record, not depicted on this survey. Scaled Data - Attention is directed to the fact that this survey may have been reduced or enlarged in size due to production. In addition, some features have not been drawn to scale, but have been drawn relative to each other r purposes of clarity. This is especially true with regard to fences and other features close to boundary lines. These etors should be taken into consideration when obtaining scaled data. Dates, Signature and Seal - The date of field survey, (below), is the last time that either field or office personnel etow) and date of signature (below), have no relationship to actual site conditions. Date of plat preparation elow) and date of signature (below), have no relationship to actual site conditions as depicted on this map. THIS JKVEY IS NOT VALID WITHOUT THE ORIGINAL SIGNATURE AND RAISED OR "BLUE" SEAL OF A CENSED LAND SURVEYOR. 	Southern Cross Surveying, LLC 101 Highway 47 South, Suite 6 Columbiana, AL 35051 Phone: 205-685-5300			
STATE OF ALABAMA COUNTY OF SHELBY , J. CLAYTON LYNCH, A REGISTERED LAND SURVEYOR IN THE STATE OF ALABAMA, HEREBY STATE THAT ALL PARTS OF THIS SURVEY AND DRAWING HAVE BEEN COMPLETED IN ACCORDANCE WITH THE CURRENT REQUIREMENTS OF THE STANDARDS OF PRACTICE FOR LAND SURVEYING IN THE STATE OF ALABAMA, TO THE BEST OF MY KNOWLEDGE, INFORMATION, AND BELIEF.	Sou	101		
J. Clayton Lynch, P.L.S. AL. Reg. No. 34331 DATED: 12-09-2016 CONSTRUCTION CONSULT (205) 368-9032	В	NTS		