#### **Lake Service Report**

Property Name: Mir		Airror Lake		AES Representative:		Greg B.	
Service Date: 5/2		20/21		Service Time:		7:40 a.m. – 10:10	
						a.m.	
Water Temperature: Visibility:		69 Degrees 30"					
Water Level		Full Pool					
Trash Collected:		Abundant					
Weather Conditions		Sunny					
Outlet Debris Cleared:		Clear					
Lake Dye Applied:		N/A	Am	ount Applied:	N/A		
Pond Fertilizer Applied:		N/A	Am	ount Applied:	N/A		
Fish Feeders Checked:		N/A	Am	ount Applied:	N/A		

Aquatic Vegetation Identified: Pennywort

Action Performed: Inspected Lake for nuisance vegetation, inspected outflow structure, man - made debris removed, plankton in bloom

Erosion/Sedimentation Observations: No substantial differences.


Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in great condition. I removed a large amount of manmade debris from the shore line of the lake. Good fish activity noted, pennywort found but not at a nuisance level, no algae at this time, water green due to planktonic bloom.

Figure 1

Picture 2







Picture 3