




OHIO HISTORIC INVENTORY

10. ERI-1646		4. Present Name(s) Clark & Eleanor Schneider Cottage		ERI-1646
2. County ERIE		5. Other Name(s) Huber Cottage		
3. Location of Negatives O.H.S.				
6. Specific Location South side of E. Lake Shore Dr., diagonally across to the east from Kelley Mansion		16. Thematic Category		Erie
7. City or Town If Rural, Township & Vicinity Kelleys Island, Ohio		17. Date(s) or Period c.1932		
8. Site Plan with North Arrow 		18. Style or Design Vernacular		
		19. Architect or Engineer Huber		Clark & Eleanor Schneider Cottage
		20. Contractor or Builder		
		21. Original Use, if apparent Residence		
		22. Present Use Residence		Huber Cottage
		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>		
		24. Owner's Name & Address, if known Clark & Eleanor Schneider 26742 Westwood Dr. Westlake, Oh. 44145		
9. U.T.M. Reference 17 7 3 5 7 8 3 0 4 6 0 5 7 2 0		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		Erie
10. Site <input type="checkbox"/> Building <input checked="" type="checkbox"/>		26. Local Contact Person or Organization Kevin Pape: KI Hist Survey		
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		27. Other Surveys in Which Included N/A		
12. Is it Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		28. No. of Stories 1		Clark & Eleanor Schneider Cottage
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> See #42		
14. District Potent'l? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		30. Foundation Material Poured concrete		
15. Name of Established District N/A		31. Wall Construction Poured concrete		Huber Cottage
		32. Roof Type & Material asph shingle/		
		33. No. of Bays Front Side		
		34. Wall Treatment Washed limestone rock		Huber Cottage
		35. Plan Shape Rectangle		
		36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/>		
		37. Condition Interior good Exterior good		Huber Cottage
		38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		
		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		
		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		Huber Cottage
		41. Distance from and Frontage on Road 16' / 67'		
		42. Further Description of Important Features (Continue on reverse if necessary) Built on a linear plan set perpendicular to the shoreline, this gabled cottage is constructed of native materials. The foundation story is composed of mortared beach stone and is supported with buttresses; it functions as a boathouse. The living story is surrounded by a framed porch, screened on two sides. The roof eaves feature exposed rafters.		
		43. History and Significance This unique summer cottage was built by Alice and W. Huber of Cleveland, O. in 1932. Along with Dr. Hummel (ERI-1647), Mr. Huber was one of a group of Cleveland professional men who formed the Sportsman's Club with headquarters in the Kelley Mansion, in 1927. Through this group he purchased the small tract of land which extends on both sides of E. Lake Shore Rd. which		Huber Cottage
		44. Description of Environment and Outbuildings The cottage is built on a slight bluff at the edge of the lake shore line, with the rear screened porch extending over the water. Its foundation is set on a large outcropping of limestone at the water's edge. The Kelley Mansion grounds lie directly opposite, across the road.		
		45. Sources of Information Eleanor Schneider Promotional Brochure: <u>An Adventure in Contentment, 1931</u> F.W. Pape H. Marchky		
		46. Prepared by Kevin Pape		Huber Cottage
		47. Organization KI Planning Commis		
		48. Date 8/85		
		49. Revision Date(s)		

50. House Type No.

Code No. Name

51. Historic Outbuildings and Dependencies

Barn Type(s)

Code No. Type

Corn Crib or Shed Smoke House Privy
 Silo Spring House Carriage House
 Summer Kitchen or Ice House

Other _____

52. Archaeological Site on Property?

Yes Skeletal material recovered when
 No water line excavated across road.
 Unsubstantiated report that foundation
 Basis for Information built upon petroglyph,
 Owner Collection (related to Erl7 ?).

Above Ground Earthworks or Mound
 Cultural Materials Noted OAI No. 33Er18

53. Farmstead Plan



54. Photo

Roll No. 25B Picture No(s). 6 & 7

42. (Cont'd)

43. (Cont'd.)

this house is built. All work done in its construction was by local workers from native materials, including limestone beach stones from Long Point. An Indian burial site was found when a water line was installed to the cottage from the main on the north side of the road, and an indian inscription found on the large rock which forms the west base of the house.